



Photo 1 – View of substantial damage to vertical stabilizer and rudder



Photo 2 – View of substantial damage to wing struts