

WPR23LA128

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Wreckage in Water (Courtesy of Pilot)



Photograph 2 - Left Wing (Courtesy of Pilot)



Photograph 3 - Left Aileron (Courtesy of Pilot)



Photograph 4 - Outboard Trailing Edge Rib Upper Flange (Courtesy of Pilot)



Photograph 5 - Outboard Trailing Edge Rib Forward Flange (Courtesy of Pilot)



Photograph 6 - Outboard Trailing Edge Rib Lower Flange (Courtesy of Pilot)



Photograph 7 - Left Wing Main Spar Separation (Courtesy of Pilot)