



Photo 1 – View of damage to left wing tip (Courtesy of Owner)