



Photo 1 – View of damage to stabilator. (photo courtesy of LEO)



Photo 2 – View of damage to fuselage. (photo courtesy of LEO)