



Photo 1 – View of Airplane (Courtesy of Pilot)



Photo 2 – Damage to the Lateral Wing Spar Carry-Through Structure (Courtesy of Pilot)