



Photo 1 – View of damage to right wing strut (courtesy of pilot)



Photo 2 – (View of damage to vertical stabilizer and rudder (courtesy of pilot))