



Photo 1 – View of substantial damage to left wing (provided by LEO)



Photo 2 – View of airplane for reference (provided by LEO)