



Photo 1 – View of damage to left aileron (Courtesy of Owner)



Photo 2 – View of damage to right aileron (Courtesy of Owner)