



Photo 1 – View of helicopter with damage to main rotor blade, tailcone and tail rotor drive system (courtesy of the FAA)