



Paul Basti
Air Safety Investigator
Western Pacific Region

Date: 11/13/2023

Subject: WPR23LA193 Record of Conversation

Contact: Lacey Utter, Pilot

The pilot stated that she could not recall what position the fuel selector was moved to. She recalled that when moving the fuel selector, the loss of power occurred, and when exiting the airplane during emergency egress, she recalls observing that the fuel selector was in the off position.

The pilot stated that there were no preaccident mechanical malfunctions or failures that would have precluded normal operation.