



Photo 1 – View of damage to left wing struts (courtesy of pilot)



Photo 2 – View of damage to vertical stabilizer and rudder (courtesy of pilot)