



Photo 1 – Rear view (Photo courtesy of Customs and Border Protection)




Photo 2 – Bottom damage tail boom (Photo courtesy of Customs and Border Protection)