

WPR23LA215

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Rear View of Wreckage (Courtesy of FAA)



Photograph 2 - Wreckage, Left Side Damage (Courtesy of FAA)



Photograph 3 - Wreckage, Front (Courtesy of FAA)



Photograph 4 - Broken Crankshaft Gear in Accessory Case (Courtesy of NTSB)



Photograph 5 - Crankshaft Gear Bolt Damage (Courtesy of NTSB)



Photograph 6 - Camshaft Gear Fragments (Courtesy of NTSB)