



Photo 1 – Airplane at accident site (courtesy of FAA)




Photo 2 – Figure of fractured bolt and nose landing gear torque link (photo courtesy of FAA)




Photo 3 – Nose landing gear strut and torque link after pickup truck collision (still from video courtesy of airplane owner)



Photo 4 – Bent tow point after accident (courtesy of FAA)