



Photo 1 –N4761A underside view. Photo courtesy of the pilot.



Photo 2 – Underside view of damage to the left and right keel beams. Photo courtesy of the pilot.