



Photo 1 – View of damage to both wings (courtesy of LEO on scene)



Photo 2 – View of damage to fuselage, vertical stabilizer, and rudder (courtesy of LEO on scene)