

WPR23LA255

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of motor-glider during aerotow ground roll (Courtesy of Flying Club)



Photograph 2 - View of separated left wing (Courtesy of FAA)



Photograph 3 - View of separated right wing without wing root spar (Courtesy of FAA)



Photograph 4 - View of left wing root and spar still affixed to right wing root spar, held together by spar pin (Courtesy of FAA)



Photograph 5 - View of left and right wing spar assembly, and failure surface (Courtesy of FAA)



Photograph 6 - Aft view of spar pin connected through spar orifice (Courtesy of FAA)