

WPR23LA270

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left leg damage



Photograph 2 -Left wing damage



Photograph 3 - Horizontal stabilizer damage