



Photo 1 – View of substantial damage to right horizontal stabilizer and elevator (owner)