



Photo 1 – forward fuselage damage (courtesy of FAA)



Photo 2 – engine mount damage (courtesy of FAA)