




Photo 1 – Aircraft logbook front cover

APLIANCE.

EENS.

H
E
Y.
C/W
JE

2R2
AD
ACH

ED IN
S

Photo 2 – Aircraft log Page 1

ALTERATIONS
(DATE NUMBER OF
SPECIFIC ENTRIES.)

Sierra Hotel Aero, Inc. 1690 Aeronca Ln, So St Paul, MN 55075 (651)306-1456
N6834W Lycoming O-320-E2A S/N L-15193-27A TSMO 1164.79 TACH 3252.79 May 31, 2023

Performed compression checks result cylinder (1) 78, (2) 80, (3) 80, (4) 78. Cleaned, inspected and gapped spark plugs. Inspected oil cooler hoses this date, no defects noted, next inspection due in 100hr/TACH 3452.79 (AD 17-14-04). Next oil cooler hoses replacement due by 04/2025 or TACH 4190.81, whichever occurs first. Drained engine oil and replaced oil filter with P/N AA48110-2. Cut and inspected old oil filter element, found to be satisfactory. Serviced engine with 7 quarts Phillips 20w50 and pint Cam Guard. Checked Timing both magnetos. Performed engine run up checks, found to be satisfactory.

I certify this engine has been inspected in accordance with a 100hr inspection and was determined to be in an airworthy condition.
Reference AD report this date

Christopher D. Gardner A&P [REDACTED]

8-15-23	3258 Tach				
Compression Test 1)		78/80	2) 77/80	3) 78/80	4) 75/80 (cold)

Photo 3 – Aircraft log Page 2

Photo 4 – Aircraft log Page 3




Photo 5 – Propeller logbook front cover

Sierra Hotel Aero, Inc. 1690 Aeronca Ln, So St Paul, MN 55075 (651)306-1456
N6834W Sensenich M74DM-0-58 S/N 6380 TSN 3252.79 TACH 3252.79 May 31, 2023

S ☐

Removed Propeller for access to change alternator. Installed propeller per Sensenich General Document 08/10/05

I certify this propeller has been inspected in accordance with a 100hr inspection and was determined to be in an airworthy condition.
Reference AD report this date.

Christopher D. Gardner A&P

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
Mech. Cert. # or Repair Station # _____		

Year: _____	Total Time in Service	Description
Date: _____		
Next Inspection Due: _____	Time Since Overhaul	
Mech. Cert. # or Repair Station # _____		

Photo 6 – Propeller page 1



Photo 7 – Back cover