

WPR23LA346

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to left wing (photo courtesy of law enforcement officer)



Photograph 2 -View of fuel selector valve pointer positions (photo courtesy of FAA inspector)