



Photo 1 –N3932G at the accident site. Photo courtesy of the owner.



Photo 2 – Left main landing gear station. Photo owner.



Photo 3 – Left main landing gear assembly. Photo owner.