



Photo 1 – View of damage to the airplane’s lower left wing (Courtesy of Operator)



Photo 2 – View of substantial damage to the lower left wing spar (Courtesy of Operator)