


WPR24FA010

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Post impact view of the airplane's nose oriented on a northerly heading



Photograph 2 - Forward to aft view of the airplane



Photograph 3 - View of ground scars and resting position of the airplane



Photograph 4 -Engine oil saturation throughout lower accessory case



Photograph 5 - Engine oil pooling above and adjacent to propeller governor adapter and air/oil separator oil return line