

Joshua Cawthra
Senior Aviation Accident Investigator
Office of Aviation Safety - Western Pacific Region

Date: January 20, 2024

Subject: WPR24FA073 - Video Camera Footage

A witness submitted security camera recordings captured from a camera mounted on his boat (see Figure 1), located in a marina about 1 mile southeast of the approach end of runway 30 at Halfmoon Bay Airport. The model of camera had an approximate 130° to 152° horizontal viewing angle.




Figure 1: Daytime view from the security camera.




Figure 2: Camera Location and Approximate Camera View Angles

Review of the submitted video that began at 1703:03, revealed that about 21 seconds (about 1703:24 PST) the sound of an airplane engine could be heard. The sound of the engine continued for about 61 seconds until approximately 1704:25 PST.

Review of the submitted video that began at 1903:35, revealed about 20 seconds (about 1903:55 PST) into the recording, the sound of an engine could be heard. The engine sound appeared to have changed in pitch/tone about 46 seconds (about 1904:21 PST) into the recording. About 1 minute, 10 seconds (about 1904:45 PST) into the recording, the sound of the engine no longer could be heard.

About 1 minute, 27 seconds (about 1904:52 PST), lights from what appears to be from an aircraft enter the upper left area of the frame of video. The lights could be seen transitioning down and to the left side out of the frame of the video 39 seconds (about 1905:32 PST) later as seen in figures 3 and 4.




Figure 3: Lights from an aircraft come into view of the camera.




Figure 4: Lights from an aircraft exit the view of the camera.