



Global Supplier of Aviation Fuel and Services

299307 FUELING

CUSTOMER JACK

AIRFIELD - IATA CODE

FLT NO.	A/C NO.	A/C TYPE	DATE
	304K		1/27 10:00
PRODUCT	FUEL REC'D	TRUCK NO.	SVC MEN
10011	8/8	75	25

TRUCK METER READING	TRUCK METER NUMBER
E N D 361658.1	
S T A R T 361642.2	

GALLONS DELIVERED

16.0

X

CUSTOMER'S AUTHORIZATION REPRESENTATIVE (SIGNATURE REQUIRED)

DESTINATION

Pacific States Aviation Inc.
101 John Glenn Dr. Concord, CA 94520
Phone (925) 685-4400 Fax (925) 687-2434
www.psaflight.com
Repair Station # CPFR948C
Tronair Authorized Service Station

Work Order: 24-19410

Opened: 1/12/2024
Accounting Close Date: 1/15/2024
Shop Close Date: 1/15/2024

Sold To:

Ship to: Jack Romanski

Aircraft Number:	N30AK	Type:RV-6	S/N: 21153
Total Time:	2,195.1	Hobbs Time:	Tach Time: 432.1 LG Cycles:
Eng# Type	S/N	Time Cycles	Prop Type Prop S/N Prop Time
1 Lycoming O-320	2754-27	2,170.2	268.0

Item: 1

Discrepancy Status: Completed

Problem:

Aircraft will not start.

Action Taken:

Removed and replaced battery with new PN : RG-25XC, SN : 41322519.

Charges This Item.		1.50 Hours @			\$
Part Number	Description	Credit	Quantity	Units	Un Ex
RG-25XC	Sealed LEAD ACID BATTERY		1.00	Each	\$
	S/N: 41322519				
	Freight		1.00		\$
				Total For This Item	\$
Miscellaneous Charges:					
				Misc Supplies	\$
				ACR	\$
Summary:					
Total Parts:	\$	530.18	Total Freight:	\$	
Misc Supplies:	\$	13.13	ACR:	\$	
Total Labor - 1.50 Hours:	\$	262.50			

Totals:

SubTotal:	\$
Sales Taxes:	\$
Total Charges:	\$
Paid-AHT-MasterCard ..	\$
Amount Remaining:	\$

Terms: Due Upon Receipt

Parts installed may not be OEM

Pacific States Aviation Inc.101 John Glenn Dr. Concord, CA 94520
Phone (925) 685-4400 Fax (925) 687-2434

www.psaflight.com

Repair Station # CPFR948C

Tronair Authorized Service Station

Work Order: 23-19381

Opened: 12/07/2023

Accounting Close Date 12/19/2023

Shop Close Date: 12/19/2023

Sold To:

Ship to: Jack Romanski

Aircraft Number: N30AK Type: RV-6 S/N: 21153

Total Time: 2,184.4 Hobbs Time: Tach Time: 421.4 LG Cycles:

Eng#	Type	S/N	Time	Cycles	Prop Type	Prop S/N	Prop Time
1	Lycoming O-320	2754-27	2,159.5				257.3

Item: 1

Discrepancy Status: Completed

Problem:

Left Main tire is flat.

Action Taken:Removed and replaced left main tube and tire with new tube PN : TU5.00-5 GL-5067B and overhauled tire PN : 5.55-5 6/30842
SN : B3D42622R1.**Note:**

This Item is covered under warranty.

Part Number	Description	Credit	Quantity	Units	Unit Price	Extended
30842-R	500-5 6 Ply Rt		1.00	Each		\$
	This part is covered under warranty.					
	S/N: B3D42622					
TU5 00-5ACL	Tube 500-5 Leakguard		1.00	Each		\$
	This part is covered under warranty.					
SubTotal For This Item:						\$
Less Warranty Parts:						\$
Total For This Item:						\$

Item: 2

Discrepancy Status: Completed

Problem:

LH brake linings worn down past limits.

Action Taken:

Removed and replaced LH Brake linings with new PN :66-106. Safetied brake caliper bolts.

Note:

This Item is covered under warranty.

Charges This Item:		0.75 Hours @			\$
					\$
Part Number	Description	Credit	Quantity	Units	Unit Price
66-106	Lining		1.00	Each	\$
	This part is covered under warranty.				
SubTotal For This Item:					\$
Less Warranty Labor:					\$

Pacific States Aviation Inc.

101 John Glenn Dr. Concord, CA 94520
Phone (925) 685-4400 Fax (925) 687-2434

www.psaflight.com

Repair Station # CPFR948C
Tronair Authorized Service Station

Less Warranty Parts: \$

Total For This Item: \$

Summary:

Total Parts: \$ [REDACTED] Total Labor - 0.75 Hours: \$

Totals:

SubTotal: \$

Less Warranty Labor: \$

Less Warranty Parts: \$

Total Charges: \$

Amount Remaining: \$

Terms: Due Upon Receipt

Parts installed may not be OEM.

Pacific States Aviation Inc.101 John Glenn Dr. Concord, CA 94520
Phone (925) 685-4400 Fax (925) 687-2434

www.psaflight.com

Repair Station # CPFR948C

Tronair Authorized Service Station

Work Order: 23-19341**Opened: 11/03/2023****Accounting Close Date: 11/21/2023****Shop Close Date: 11/21/2023**

Sold To: [REDACTED]

Ship to: Jack Romanski

Aircraft Number: N30AK Type: RV-6 S/N: 21153

Total Time: 2,184.4 Hobbs Time: Tach Time: 421.4 LG Cycles:

Eng#	Type	S/N	Time	Cycles	Prop Type	Prop S/N	Prop Time
1	Lycoming O-320	2754-27	2,159.5				257.3

Item: 1

Discrepancy Status: Completed

Problem:

Condition Inspection Airframe

Action Taken:

Performed yearly condition inspection IAW FAR part 43 appendix D. I certify this aircraft has been inspected in the scope and detail of FAR 43 Appendix D, and found to be in a condition safe for operation.

Charges This Item:

8.00 Hours @ [REDACTED] \$ [REDACTED]

Total For This Item: \$ [REDACTED]

Item: 2

Discrepancy Status: Completed

Problem:

Perform 100Hr engine inspection.

Action Taken:

Performed 100 hour engine inspection IAW FAR 43 Appendix D. Researched ADs through 11/20/2023. Performed oil change and serviced the engine with 8qts of Phillips XC20W50 and new oil filter P/N-AA48110-2. Cut open and inspected the oil filter for any FOD. None found at this time. Cyl Compressions: Cyl #1- 73/80, Cyl #2- 76/80, Cyl #3- 71/80, Cyl #4- 78/80, I certify this Engine has been inspected IAW 100 Hr. inspection and found to be in airworthy condition.

Charges This Item:

5.00 Hours @ [REDACTED] \$ [REDACTED]

Part Number	Description	Credit	Quantity	Units	Unit Price	Ex
M674	Spark Plug Gasket		8.00	Each	[REDACTED]	\$ [REDACTED]
AA48110-2	Oil Filter		1.00	Each	[REDACTED]	\$ [REDACTED]
MX-PHILLIPS-XC-20W/50	Oil - Engine P/N 1045457		8.00	Each	[REDACTED]	\$ [REDACTED]
						Total For This Item: \$ [REDACTED]

Item: 3

Discrepancy Status: Completed

Problem:

Perform 100Hr propeller inspection.

Action Taken:

Performed 100 hour propeller inspection IAW FAR 43 Appendix D. Researched ADs through 11/20/2023. I certify this propeller has been inspected IAW 100 Hr. propeller inspection and was determined to be in airworthy condition.

Charges This Item:

1.00 Hours @ [REDACTED] \$ [REDACTED]

Total For This Item: \$ [REDACTED]

Pacific States Aviation Inc.
 101 John Glenn Dr. Concord, CA 94520
 Phone (925) 685-4400 Fax (925) 687-2434
 www.psaflight.com
 Repair Station # CPFR948C
 Tronair Authorized Service Station

Item: 4

Discrepancy Status: Completed

Problem:

Mags out of time.

Action Taken:

Timed magnetos to 25° before TC.

Charges This Item:

0.50 Hours @ [REDACTED] \$

Total For This Item: \$

Item: 5

Discrepancy Status: Completed

Problem:

Oil leak from filler neck.

Action Taken:

Tightened oil filler neck and safetied. No discrepancies found after leak check.

Charges This Item:

0.25 Hours @ [REDACTED] \$

Total For This Item: \$

Item: 6

Discrepancy Status: Completed

Problem:

Oil leak from push rod tubes.

Action Taken:

Removed and replaced push rod TUBES with new seals PN : LW18661 and PN : 70310. Performed leak check. No further discrepancies found at this time.

Charges This Item:

2.00 Hours @ [REDACTED] \$

Part Number	Description	Credit	Quantity	Units	Unit Price	Extended
70310	Seal		7.00	Each	[REDACTED]	\$
LW18661	Seal		4.00	Each	[REDACTED]	\$
LW12272	Plate		4.00	Each	[REDACTED]	\$
75906	Gasket Rocker Box		4.00	Each	[REDACTED]	\$
SL70310	70310 O-Ring		1.00	Each	[REDACTED]	\$
Total For This Item:						\$

Item: 7

Discrepancy Status: Completed

Problem:

Oil leak on RH mag adapter.

Action Taken:

Tightened nuts after mag timing, ans no leaks found after leak check.

Charges This Item:

0.25 Hours @ [REDACTED] \$

Total For This Item: \$

Item: 8

Discrepancy Status: Completed

Problem:

Leading edge of LH flap rubbing on wing.

Action Taken:

re bent leading edge flap to give Clearance from the wing.

Charges This Item:

2.00 Hours @ [REDACTED] \$

Total For This Item: \$

Item: 9

Pacific States Aviation Inc.
 101 John Glenn Dr. Concord, CA 94520
 Phone (925) 685-4400 Fax (925) 687-2434
 www.psaflight.com
 Repair Station # CPFR948C
 Tronair Authorized Service Station

Discrepancy Status: Completed

Problem:

Cylinder # 3 push rod TUBE cracked.

Action Taken:

Removed and replaced push rod tube with new PN : 68987.

Charges This Item:		1.00 Hours @			\$	
Part Number	Description	Credit	Quantity	Units	Unit Price	Extended
68987	Tube		1.00	Each	\$	
Total For This Item:						\$

Item: 10

Discrepancy Status: Completed

Problem:

LH fuel gage IN OP.

Action Taken:

Owner did not approve for repairs.

Total For This Item:						\$	N/C
----------------------	--	--	--	--	--	----	-----

Item: 11

Discrepancy Status: Completed

Problem:

Bottom cowl has hole.

Action Taken:

Owner did not approve for repairs.

Total For This Item:						\$	N/C
----------------------	--	--	--	--	--	----	-----

Item: 12

Discrepancy Status: Completed

Problem:

RH Main brake lining worn to limits.

Action Taken:

Removed and replaced brake linings with new PN : 066-10600.

Charges This Item:		1.00 Hours @			\$	
Part Number	Description	Credit	Quantity	Units	Unit Price	Extended
066-10600	Cleveland Brake Lining		2.00	Each	\$	
Total For This Item:						\$

Miscellaneous Charges:

Misc Supplies:						\$
ACR:						\$

Summary:

Total Parts:	\$		Misc Supplies:	\$
ACR:	\$		Total Labor - 21.00 Hours:	\$

Totals:

SubTotal:	\$
Sales Taxes:	\$
Total Charges:	\$
Paid-AHT-MasterCard	\$
Amount Remaining:	\$

Terms: Due Upon Receipt

Parts installed may not be OEM.