

WPR24FA080

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Flight path track photograph




Photograph 2 - Left side view of airplane at accident site



Photograph 3 - View of airplane at the engine exam.



Photograph 4 - View of engine separated from airframe (Courtesy of Lycoming)



Photograph 5 - View of carburetor damage (Courtesy of Lycoming)



Photograph 7 - View of detached fuel line