

WPR24FA104

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident airplane in an open field



Photograph 2 - View of damaged fuselage, wings and tailcone



Photograph 3 - View of recovered airplane in hangar for examination



Photograph 4 - View of damaged propeller assembly



Photograph 5 - View of right-wing during examination



Photograph 6 - View of left-wing during examination



Photograph 7 - View of fuselage, empennage, and tailcone during examination



Photograph 8 - View of engine during examination