



WPR24FA105

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Southeast flight track to accident site



Photograph 2 - View of cut static high-tension line between towers



Photograph 3 - View of accident site between high-tension towers



Photograph 4 - View of engine at end of accident trench



Photograph 5 - View of engine at accident site



Photograph 6 - View of engine prior to engine examination