

WPR24FA227

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of accident site (Courtesy of Utah Co Sheriff)



Photograph 2 - View of control locking devise (Courtesy of Utah Co Sheriff)



Photograph 3 - View of engine examination