

WPR24FA298

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Main wreckage at accident site.



Photograph 2 - Main wreckage at accident site.



Photograph 3 - Main wreckage at accident site. (Courtesy of FAA)



Photograph 4 - Propeller blade partially dug out at accident site. (Courtesy of FAA)



Photograph 5 - Main landing gear assembly. (Courtesy of FAA)



Photograph 6 - Engine at follow up examination.



Photograph 7 - Engine at follow up examination.