

WPR24FA309

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Forward quartering view of N313YK



Photograph 2 - N313YK left wing



Photograph 3 - Propeller fragments in left wing of N313YK



Photograph 4 - Partially separated vertical stabilizer from N313YK at accident site



Photograph 5 - N313YK Cockpit and canopy at accident site




Photograph 6 - Rear quartering view of N5287 at accident site




Photograph 7 - Left wing of N5287 at accident site




Photograph 8 - N5287 broken propeller blades at accident site



Photograph 9 - Flight track of Yak52 (N5287) and accident site locations



Photograph 10 - CJ-6A (N313YK) damage figure



Photograph 11 - Yak 52 (N5287) damage figure