



Eric M. Gutierrez
Air Safety Investigator
Western Pacific Region

Date: September 8, 2022

Subject: WPR24LA021, Memorandum for Record

Contact: Natalia Font Velez, Pilot

The following is a synopsis of the information provided by Ms. Font Velez in an e-mail correspondence.

While struggling to turn base, due to the sudden violent wind, it forced her to extend the downwind leg of the airport traffic pattern. She was attempting to stabilize the airplane. During the second attempt to turn base, the airplane struck a wire and then impacted terrain.