


WPR23LA023

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of recovered fuselage (Courtesy of the FAA).



Photograph 2 - Disconnected carburetor float bowl vent line 1/3 side.



Photograph 3 - Upper spark plugs.



Photograph 4 - Recovered airframe and engine.