

WPR24LA038

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Front view of accident airplane with missing windshield (Courtesy of FAA)



Photograph 2 - View of accident airplane empennage (Courtesy of FAA)



Photograph 3 - View of broken rudder trim tab rod end (Courtesy of FAA)