



Photo 1 – View of damage to windscreen (Courtesy of FAA)



Photo 2 – View of left side engine cowling (Courtesy of IIC)



Photo 3 – View of right side cowling pin failure (Courtesy of FAA)



Photo 4 – View of right side cowling attachment composite failure (Courtesy of FAA)