

WPR24LA070


INVESTIGATION PHOTOGRAPHS



Photograph 1 - Tail view at accident site (Courtesy of FAA)




Photograph 2 - Forward view of accident site (Courtesy of FAA)



Photograph 3 - Engine received with compressor bleed-off valve (BOV) center at PWC.



Photograph 4 - Compressor bleed-off valve removed. (Courtesy of PWC)



Photograph 6 - BOV piston removed from housing. (Courtesy of PWC)