

WPR24LA079

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of right horizontal stabilizer damage (Courtesy of Pilot)