

WPR24LA085

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Forward to aft view of the accident airplane (Courtesy of Airport Operations)



Photograph 2 - View of substantial damage to the airplane's right wing and fuselage (Courtesy of Airport Operations)



Photograph 3 - View of the damage sustained to the left side of the airplane (Courtesy of Airport Operations)




Photo 5 -Distance between the airplane's wake vortex encounter and runway 20L ~450 ft