

WPR24LA100

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right Aileron Damage (Courtesy of FAA)



Photograph 2 - Right Main Tire Sidewall (Courtesy of FAA)



Photograph 3 - Right Main Tire Tread (Courtesy of FAA)