

WPR24LA102

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of Damaged Wing (Courtesy of FAA)



Photograph 2 - View of Damage to the Tail (Courtesy of FAA)