

WPR24LA138

INVESTIGATION PHOTOGRAPH



Photograph 1 - View of substantial damage to main and tail rotor systems (Courtesy of Operator)