

WPR24LA141

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of substantial damage to the left side empennage (Courtesy of Operator)



**Photograph 2 - Top view of substantial damage right side empennage and right wing
(Courtesy of Operator)**