

WPR24LA153

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of left side of motorglider. (Courtesy of airport manager)



Photograph 2 - View of aft fuselage damage. (Courtesy of airport manager.)



Photograph 3 - View of empennage damage. (Courtesy of airport manager)