

WPR24LA157

INVESTIGATION PHOTOGRAPHS-POSTACCIDENT EXAMINATION



Photograph 1 - Accident airplane, alternator circuit breaker. (Courtesy of the Mechanic)



Photograph 2 - Engine test run, left side instrument panel. (Courtesy of the Mechanic)



Photograph 3 - Landing gear emergency extension handle. (Courtesy of the Mechanic)



Photograph 4 - Left horizontal stabilizer and elevator damage. (Courtesy of the Mechanic)



Photograph 5 - Left horizontal stabilizer and elevator damage. (Courtesy of the Mechanic)