



Photo 1 –N7838W engine area. Photo NTSB.



Photo 2 -N7838W Left-side view. Photo insurance provider.



Photo 3 -N7838W at the accident site, front view. Photo insurance provider.