

WPR24LA183

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of damage to main rotor blades (Courtesy of Flight Instructor)



Photograph 2 - View of damage to tail boom and vertical stabilizer (Courtesy of Flight Instructor)