

WPR24LA186

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Left-side view at accident site (Courtesy of the owner)



Photograph 2 - Left side view of wing at accident site (Courtesy of the owner)



Photograph 3 - Left wing leading edge at accident site (Courtesy of the owner)