



Photo 1 – N17304 at the accident site. Photo courtesy of Airport Operations



Photo 2 – Substantially damaged horizontal stabilizer. Photo courtesy of Airport Operations